



VICTROLA™

MODEL: VPM-254

M1 MONITORS

POWER SUPPLY: AC 100-240V~50/60HZ

POWER CONSUMPTION: 60W


FCC ID: 2AFHW-VPM254 | IC: 9577A-VPM254

CAN ICES-3(B)/NMB-3(B)

MADE IN CHINA | WWW.VICTROLA.COM

MANUFACTURE DATE: 07/2021

SERIAL NUMBER:



CAUTION/ATTENTION:

RISK OF ELECTRIC SHOCK. DO NOT
OPEN. / ATTENTION RISQUE DE
CHOC ÉLECTRIQUE. NE PAS OUVRIR.



CAUTION / ATTENTION:

TO REDUCE THE RISK OF ELECTRIC SHOCK, DO NOT REMOVE COVER (OR BACK). NO USER SERVICEABLE PARTS INSIDE. REFER SERVICING TO QUALIFIED SERVICE PERSONNEL. / POUR RÉDUIRE LE RISQUE DE CHOC ÉLECTRIQUE, NE PAS RETIRER LE COUVERCLE (OU L'ARRIÈRE). AUCUNE PIÈCES À L'INTÉRIEUR RÉPARABLES. CONFIER L'ENTRETIEN À UN PERSONNEL QUALIFIÉ.



801361



CONFORMS TO UL STD.62368-1
CERTIFIED TO CSA STD.C22.2
NO.62368-1



THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.



MODEL: VPM-254
M1 MONITORS
POWER SUPPLY: AC 100-240V~50/60Hz
POWER CONSUMPTION: 60W
FCC ID: 2AFHW-VPM254 | IC: 9577A-VPM254
CAN ICES-3(B)/NMB-3(B)
MADE IN CHINA | WWW.VICTROLA.COM
MANUFACTURE DATE: 07/2021
SERIAL NUMBER:



CAUTION/ATTENTION:

RISK OF ELECTRIC SHOCK. DO NOT OPEN. / ATTENTION RISQUE DE CHOC ÉLECTRIQUE. NE PAS OUVRIR.



CAUTION / ATTENTION:
TO REDUCE THE RISK OF ELECTRIC SHOCK, DO NOT REMOVE COVER (OR BACK). NO USER SERVICEABLE PARTS INSIDE. REFER SERVICING TO QUALIFIED SERVICE PERSONNEL. / POUR RÉDUIRE LE RISQUE DE CHOC ÉLECTRIQUE, NE PAS RETIRER LE COUVERCLE (OU L'ARRIÈRE). AUCUNE PIÈCES À L'INTÉRIEUR RÉPARABLES. CONFIER L'ENTRETIEN À UN PERSONNEL QUALIFIÉ.



801361



CONFORMS TO UL STD. 62368-1
CERTIFIED TO CSA STD. C22.2
NO. 62368-1



THIS DEVICE COMPLIES WITH PART 15 OF THE FCC RULES. OPERATION IS SUBJECT TO THE FOLLOWING TWO CONDITIONS: (1) THIS DEVICE MAY NOT CAUSE HARMFUL INTERFERENCE, AND (2) THIS DEVICE MUST ACCEPT ANY INTERFERENCE RECEIVED, INCLUDING INTERFERENCE THAT MAY CAUSE UNDESIRE OPERATION.