



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

**From:** Generic Office of Engineering Technology [mailto:oeotech@fccsun27w.fcc.gov] **Sent:** Thursday, June 15, 2006 1:33 PM **To:** marianne@atcb.com **Subject:** Response to Inquiry to FCC (Tracking Number 78802) - harmonic levels of intentional radiator - beyond 10th

The items indicated above must be submitted before processing can continue on the above referenced FCC DoN UCLASS RIES. Provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

**Inquiry:** Timothy R. This question is regarding the harmonic levels of an intentional radiator. Part 15 indicates that the level of the unwanted emissions shall not exceed the fundamental. Does this also include the harmonics of the submitted information? I have a few comments on the above referenced Application. Please note they will increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.

**Response:** Please provide a separate test configuration photograph exhibit.

**Response provided 1/19/2007:** information required by 15.19(a)(3) Yes, this includes harmonics beyond the tenth harmonic. The field strength of the unwanted

**Response: provided 2/28/2007** radiated emissions (harmonic emissions in this case) may not exceed that of the fundamental.

3) Is confidentiality required on any exhibits that are proprietary (i.e. schematics, block diagram, operational description)? We did not receive a cover letter regarding a confidentiality request. Note the request should be signed by the contact on record with the FCC (i.e. Peter Scharpf).

**Response provided 1/11/2007:** Note that Peter Scharpf is now no longer with the Company. Generally the FCC desires sufficient photographs as to sufficient views of the internal construction to define component placement and chassis assembly of the entire device. It appears additional internal photographs may be necessary. Please review. **Response: Please review the internal device photographs provided 3/1/2007**

7) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

8) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

9) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

10) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

11) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

12) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

13) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

14) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

15) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

16) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

17) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

18) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

19) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

20) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

21) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

22) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

23) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

24) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

25) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

26) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

27) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

28) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

29) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

30) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

31) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

32) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

33) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**

34) The harmonics of the 13.56 TX crystal. Note that many harmonics of the 13.56 MHz are not in compliance with 15.215(b). Assuming a 40 dB roll off, 3 meter results would appear to be around 33.4 dBuV/m for the fundamental. Many harmonics exceed this level. Also, please see attached interpretation on the following page 3 which is relevant to this. **Response: There was a measurement error. Please see revised report WOC606529-1 and 4-3 Rev A**