

## Mike Kuo

---

**From:** daphne.liang [daphne.liang@tw.ccsemc.com]  
**Sent:** Thursday, April 20, 2006 12:05 AM  
**To:** lucy.tsai  
**Cc:** application; Mike Kuo  
**Subject:** Re : Microlink Communications Inc., FCC ID: QVZHHB700-3 , Assessment NO.: AN06T5681, Notice#1-- Updated(0420)  
**Attachments:** HHB700-3\_User manual(0420).pdf; HHB700-3\_Label Location(0420).pdf; HHB700-3\_Setup Photo(0420).pdf; HHB700-3\_Report(RP1-1)0420.pdf

Hi Lucy:

Please find the attached for updated files(0420) and see the belowing reply.  
Thank you so much!

BEST REGARDS

Daphne Liang / 梁鈺如 4/20/2006  
Certification Team Leader / Certification Dept.

---

Compliance Certification Services Inc.  
Rm.258, Bldg.17, No.195, Sec.4, Chung  
Hsing Rd., Chutung, Hsinchu, Taiwan, R.O.C.  
Tel: 886-3-5910068 EXT: 502  
Fax: 886-3-5825720  
E-mail: daphne.liang@tw.ccsemc.com  
URL: <http://www.ccsemc.com.tw>

**lucy.tsai**

蔡文君

收件人: daphne.liang/ccsemc@ccsemc, application/ccsemc@ccsemc

副本抄送: Mike Kuo <mike.kuo@ccsemc.com>

主旨: Microlink Communications Inc., FCC ID: QVZHHB700-3 , Assessment NO.: AN06T5681, Notice#1

2006/04/20 09:59 AM

Hi Daphne,

Please address the following questions.

Best Regards,

Lucy

----- 轉呈者 lucy.tsai/ccsemc 於 2006/04/20 09:30 AM -----

<mike.kuo@ccsemc.com>

4/25/2006

2006/04/19 06:42 PM

收件人： <mike.kuo@ccsemc.com>

副本抄送： <lucy.tsai@tw.ccsemc.com>

主旨： Microlink Communications Inc., FCC ID: QVZHBB700-3 , Assessment NO.: AN06T5681, Notice#1

1. Three different FCC IDs appeared in test report (FCC ID:QVZHBB700-3), label location (FCC ID:QVZHBB700U3-1) and user manual(FCC ID:QVZHBB700). Please check which one is correct and make proper correct as well.

Ans:Please find the attached for updated(0420) user's manual & Label Locations.

2. Page 12 of user manual also shows a FCC logo which doesn't agree with submission. Please remove.

Ans:Puts this LOGO on the manual is for customer's request. They asking us perform the FCC 15B testing and

persist must put this FCC LOGO in USER'S MANUAL.Can CCS-TCB accept that??

3. Setup photos indicated several modes were investigated, for example, RF mode, charging mode and etc., yet only one set of test result was reported. Please explain.

Ans:Sorry,we have revised the test report as just for RF mode. Please find the attached for updated(0420)

test report & setup photo.

4. Please provide antenna conducted test setup photo.

Ans:Please find the attached for updated(0420) setup photo.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

---

This e-mail transmission is confidential and intended solely for being reviewed by the recipient(s) identified above. If you are not an identified recipient, please ensure that this communication remains confidential and promptly return it to the sender. Please contact immediately by phone (Tel: 886-2-2299-9720) for any problem with this transmission, Thank you for your attention.

4/25/2006