


385mm



Caveats

 $|\Theta|$

- 4.Do not use this headset during a thunderstorm to avoid irregular function and increased risk of electric shock. 5.Do not use harsh chemicals or strong deterge nts to

Notes: Please arrange using time properly since your hearing may be damaged by using the device for along time.

For any after service, please contact local distributor

Web: www.gcy.com

Manufacturer: Dongguan Hele Electronics Co.,Ltd. Address: Dalingya Industrial Zone, Daojiao Town, Dongguan City, Guangdong Province(QC

Environmental Zone, Dalingya No.5, Yuehu Road)

FCC Statement

Changes or modifications not expressly approved by the party esponsible for compliance could void the user's authority to operate the equipment.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the

instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- -- Increase the separation between the equipment and receiver - Connect the equipment into an outlet on a circuit different from

that to which the receiver is connected. -- Consult the dealer or an experienced radio/TV technician for

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions (1)this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.