



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

July 21, 2004

RE: Evermore Systems

FCC ID: SYBSSL1 or SBYSSL1

After a review of the submitted information, I have a few comments on the above referenced Application.

Administrative Issues:

- 1) Your response states that 2431 MHz was correct frequency, but the only corrected exhibit appears to be the 731 form which was changed from 2431 to 2432 MHz. Also, the operational description has not been changed. We are confused. What is the correct frequency?
- 2) Please provide a corrected users manual that includes the information for 15.105.
- 3) Since DoC is being applied for the PC peripheral portion of the product, please provide an updated labeling exhibit that also includes the proper DoC labeling.
- 4) FYI.....The manufacturer is still response for making sure that DoC information previously mentioned gets added to the users manual.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.