


THIS DOCUMENT CONTAINS INFORMATION OF A PROPRIETARY NATURE TO FENDER MUSICAL INSTRUMENTS AND IS SUBMITTED TO YOU IN CONFIDENCE AND SHALL NOT BE DISCLOSED OR TRANSMITTED TO OTHERS WITHOUT AUTHORIZATION FROM FENDER MUSICAL INSTRUMENTS CORP.

REVISIONS			
REV	DESCRIPTION	BY	DATE
A	PR601	KT	3/13/2007
B	EC4347 NEW TEXT AND GRAPHICS.	KT	1/19/2010




- 8. TEXT AND GRAPHICS TO BE: WHITE.
- 7. BACKGROUND TO BE: BLACK.
- 6. MATERIAL TO BE: -.010" VELVET/MATTE POLYCARBONATE SUBSURFACE SCREEN PRINTED WITH 3M 467MP PRESSURE SENSITIVE ADHESIVE, FAR SIDE.
- 5. ALL ARTWORK TO BE SUPPLIED BY FENDER R&D.
- 2. SAMPLES OF FIRST PARTS MUST BE APPROVED BY FENDER R&D BEFORE STARTING PRODUCTION. QTY. 3 UNLESS OTHERWISE SPECIFIED.
- 1. ALL DIMENSIONS ARE IN INCHES.

NOTES: UNLESS OTHERWISE SPECIFIED.

ANY PART SUPPLIED FOR USE IN ANY FENDER PRODUCT MUST CONFORM TO THE EUROPEAN RoHS DIRECTIVE.

COPYRIGHT -2010- FENDER MUSICAL INSTRUMENTS CORP.



GENERAL TOLERANCES UNLESS OTHERWISE SPECIFIED	
ENGLISH	
FRACT-----	± 1/32
.X-----	± .050
.XX-----	± .020
.XXX-----	± .010
HOLE DIA.-----	+0.005-.001
WOOD HOLE DIA.---	± .005
METRIC	
.X-----	± 01.0
.XX-----	± 0.50
.XXX-----	± 0.25
HOLE DIA.-----	+0.13 -0.03
ANGLES	
ANGLES-----	± 0.5°
UNMARKED ANGLES --	90°
DO NOT SCALE DRAWING	

ENGINEER BYRON TANIGAWA		FENDER MUSICAL INSTRUMENTS CORP. RESEARCH & DEVELOPMENT CORONA, CALIFORNIA U.S.A.	
DRAWN KIMBO TIPPETT		TITLE LABEL SAFETY WRLS SYS HH	
DATE 1/12/2010			
CHKD	S.M.E. (OPT)	MGR/DIR (OPT)	P.E.
DATE	DATE	DATE	DATE
SIZE A	PART NUMBER 601TMI008		SPECS B
FILE NAME: 601TMI008 SPECS 1-2-B		SCALE: 1/1	SHEET: 1 of 2

Label Location – UHF WRLS HH



Label will be placed
in Battery compartment
as shown.

This statement will be placed in User's Manual:

This device complies with part 15 of the FCC Rules and with RSS-210 of Industry Canada. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.