

To: Mark Brennan
E-Mail: doug.blodgett@gm.com
From: Doug Young
Date: September 26, 2018

Subject: Request for Info - File # 0178-EX-CM-2018

Message:

There were previously six repeaters listed at slightly different coordinates. There are now four listed at the same exact coordinates. This needs to be cleared up. Are the powers now in ERP or EIRP? There are three repeaters now listed as 31.6 pW and one listed as 50.1 pW. I can't match them as ERP values equivalent to the EIRP values in the document of calculations. Please clear this up.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of September 26, 2018 may result in application dismissal pursuant to Section 5.67 and forfeiture of the filing fee pursuant to Section 1.1108.

DO NOT Reply to this email by using the 'Reply' button. In order for your response to be processed expeditiously, you must upload your response via the Internet at <https://apps.fcc.gov/oetcf/els/index.cfm> by clicking on the "Reply to Correspondence" hyperlink.

Responses to this correspondence must contain the Reference number : 44161