

From: Mike Miller

To: Nimesh Sangani
Date: October 11, 2020

Subject: Additional Information Request

Message:

The DC motor is missing from the original ODAR submission, because it was not part of the spacecraft at that time. PRCUNAR submitted a new component list earlier this year, and we revised said ODAR.

With respect to the survivability of the motor, DAS analysis says that the DC motor survives to the ground, but the kinetic energy is low as compared to the limit of 15 joules.