



Internal Photographs Project No.:4791353869-1







Internal View of EUT-2








Internal View of EUT-4








Internal View of EUT-6











Internal View of EUT-8









Internal View of EUT-10








Internal View of EUT-12








This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.


13 3666

Ĵ












Internal View of EUT-18







Internal View of EUT-20





Internal View of EUT-21

