
Report No.: AGC01559211102AP02 Page 1 of 8

INTERNAL PHOTOS

OPEN VIEW OF EUT (FIGURE 1)




VIEW OF BATTERY




Report No.: AGC01559211102AP02 Page 2 of 8

INTERNAL VIEW OF EUT (FIGURE 1)




INTERNAL VIEW OF EUT (FIGURE 2)




Report No.: AGC01559211102AP02 Page 3 of 8

INTERNAL VIEW OF EUT (FIGURE 3)




INTERNAL VIEW OF EUT (FIGURE 4)




Report No.: AGC01559211102AP02 Page 4 of 8

INTERNAL VIEW OF EUT (FIGURE 5)




INTERNAL VIEW OF EUT (FIGURE 6)




Report No.: AGC01559211102AP02 Page 5 of 8

INTERNAL VIEW OF EUT (FIGURE 7)




INTERNAL VIEW OF EUT (FIGURE 8)




Report No.: AGC01559211102AP02 Page 6 of 8


INTERNAL VIEW OF EUT (FIGURE 9)




INTERNAL VIEW OF EUT (FIGURE 10)




INTERNAL VIEW OF EUT (FIGURE 11)



INTERNAL VIEW OF EUT (FIGURE 12)



INTERNAL VIEW OF EUT (FIGURE 13)



INTERNAL VIEW OF EUT (FIGURE 14)

