
C 58 59 60 0 3 3 64 65 66 67 89 15 16 17 18 19 20 3 29 27 28 69

1. INTERIOR PHOTOGRAPHS

Fig. 1




This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 1 of 4


SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.



Fig. 3



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 2 of 4







Fig. 6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 3 of 4 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 4 of 4