
5. Test setup photograph

5.1. Photos of power line conducted emission test



5.2. Photos of radiated emission test



Report No: DDT-RE130281