

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341

Internal Photographs



Figure 1. Front Control Panel, Solder Side

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341



Figure 2. Front Panel, Button Side

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341




Figure 3. RF Radio Circuit (Close Up, RF shield removed)

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341



Figure 4. Solder Side of Main Circuit Board

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341



Figure 5. Component Side of Main Circuit Board

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341




Figure 6. CD Player Control Board, Top

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341




Figure 7. CD Player Control Board, Back

US Tech Test Report:
Report Number:
Customer:
FCC ID:
Issue Date:
Model:

FCC Part 15.249
14-0063
Electronica Clarion S.A. de C.V
2ABGYBTD33-CLARION
April 14, 2014
BTD3341



Figure 8. SC Card Holder, Top