

Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405








Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405 453 of 465







Report No.: AR/2020/C000405








Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405







Report No.: AR/2020/C000405

Page: 459 of 465

#### **Duty Cycle**

#### **Test Result**

Test Mode	TX Freq. [MHz]	Duty cycle [%]	Duty cycle Correction Factor[dB]
11A	Ant 1: CH149, CH157, CH165	98.09	0.08
11N20	Ant 1: CH149, CH157, CH165	97.95	0.09
11N40	Ant 1: CH151, CH159	95.92	0.18
11AC20	Ant 1: CH149, CH157, CH165	97.96	0.09
11AC40	Ant 1: CH151, CH159	95.92	0.18
11AC80	Ant 1: CH155	92.00	0.36






Report No.: AR/2020/C000405

460 of 465 Page:


**Test Graphs** 








Report No.: AR/2020/C000405








Report No.: AR/2020/C000405








Report No.: AR/2020/C000405








Report No.: AR/2020/C000405







Report No.: AR/2020/C000405



The End

