

US Tech Test Report

FCC ID:

Test Report Number:

Issue date:

Customer:

Model:

FCC Part 15.209/249

2ALIF-STR02

19-0453

December 3, 2019

ElectronixIQ

STINGER 2

EXTERNAL PHOTOGRAPHS



Figure 1. Top View

US Tech Test Report

FCC ID:

Test Report Number:

Issue date:

Customer:

Model:

FCC Part 15.209/249

2ALIF-STR02

19-0453

December 3, 2019

ElectronixIQ

STINGER 2



Figure 2. Side 1 View

US Tech Test Report

FCC ID:

Test Report Number:

Issue date:

Customer:

Model:

FCC Part 15.209/249

2ALIF-STR02

19-0453

December 3, 2019

ElectronixIQ

STINGER 2




Figure 3. Bottom View

US Tech Test Report

FCC ID:

Test Report Number:

Issue date:

Customer:

Model:

FCC Part 15.209/249

2ALIF-STR02

19-0453

December 3, 2019

ElectronixIQ

STINGER 2




Figure 4. Side 2 View

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2ALIF-STR02
19-0453
December 3, 2019
ElectronixIQ
STINGER 2



Figure 5. Back of EUT

US Tech Test Report
FCC ID:
Test Report Number:
Issue date:
Customer:
Model:

FCC Part 15.209/249
2ALIF-STR02
19-0453
December 3, 2019
ElectronixIQ
STINGER 2



Figure 6. Front of EUT