






2DH1\_Ant1\_2402\_30~1000







2DH1\_Ant1\_2402\_1000~26500




2DH1\_Ant1\_2441\_0-Reference











3DH1\_Ant1\_2402\_30~1000




3DH1\_Ant1\_2402\_1000~26500




3DH1\_Ant1\_2441\_0-Reference






3DH1\_Ant1\_2480\_30~1000




3DH1\_Ant1\_2480\_1000~26500



## APPENDIX A: PHOTOGRAPHS OF TEST SETUP

Antenna Requirement



Conducted Emissions at AC Power Line (150kHz-30MHz)





### Radiated Spurious Emissions





## APPENDIX B: PHOTOGRAPHS OF EUT













































----END OF REPORT----

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.