1. INTERIOR PHOTOGRAPHS



Fig.1




Fig.2

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 1 of 6

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ANO6Q20 Report No.: LCS170801219AE



Fig.3



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID: 2ANO6Q20

Report No.: LCS170801219AE




Fig.5




Fig.6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ANO6Q20 Report No.: LCS170801219AE




Fig.7




Fig.8

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID: 2ANO6Q20

Report No.: LCS170801219AE




Fig.9




Fig.10

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 6 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD. FCC ID: 2ANO6Q20

Report No.: LCS170801219AE




Fig.11

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 6 of 6