




Internal photos



Note:

The solder joint test was cancelled at position 1, the line layout was optimized at position 2, and the antenna was lengthened at position 3



Note:

The solder joint test was cancelled at position 1, and the line layout was optimized at position 2

