
1. INTERIOR PHOTOGRAPHS



Fig. 1



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 1 of 7

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig. 3




Fig. 4

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 2 of 7

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID:2AP4M-C8




Fig. 5




Fig. 6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 3 of 7




Fig. 8

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 4 of 7

FCC ID:2AP4M-C8

SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig. 9




Fig. 10

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 5 of 7




Fig. 11




Fig. 12

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 6 of 7 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.




Fig. 13

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd.. Page 7 of 7