


**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**




**Photo 1**




**Photo 2**

**Worst Case Position**


**ECU**  
**Below 30 MHz**  
**X-axis**  
**Above 30 MHz**  
**Horizontal: X-axis / Vertical: X-axis**  
**X-axis**



**Y-axis**




**Z-axis**



**LF Antenna**  
**Below 30 MHz**  
**X-axis**  
**Above 30 MHz**  
**Horizontal: X-axis / Vertical: X-axis**  
**X-axis**



**Y-axis**



**Z-axis**



**Worst Case Position**

**Immobilizer Antenna**

**Below 30 MHz**

**X-axis**

**Above 30 MHz**

**Horizontal: X-axis / Vertical: X-axis**

**X-axis**



**Y-axis**



**Z-axis**



**Worst case position**



**With transponder key attached**



**Without transponder key attached (Worst)**

**End of Report**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124