



Appendix II

Internal Photographs


Internal View of EUT-1




Internal View of EUT-2



Internal View of EUT-3




Internal View of EUT-4



Page 3 of 12

Internal View of EUT-5




Internal View of EUT-6



Page 4 of 12

Internal View of EUT-7




Internal View of EUT-8




Page 5 of 12

Internal View of EUT-9




Internal View of EUT-10




Page 6 of 12


Internal View of EUT-11




Internal View of EUT-12



Internal View of EUT-13




Internal View of EUT-14




Page 8 of 12

Internal View of EUT-15




Internal View of EUT-16




Page 9 of 12

Internal View of EUT-17




Internal View of EUT-18



UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Page 10 of 12

Internal View of EUT-19



Internal View of EUT-20



Page 11 of 12

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Internal View of EUT-21



Internal View of EUT-22



Page 12 of 12