







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (41) / (373) Pages



ANT1\_802.11n\_HT20\_UNII 1




ANT1\_802.11n\_HT20\_UNII 2A






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (42) / (373) Pages



ANT1\_802.11n\_HT20\_UNII 2C






ANT1\_802.11n\_HT20\_UNII 3






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (43) / (373) Pages



**ANT2\_802.11n\_HT20\_UNII 1**






**ANT2\_802.11n\_HT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (44) / (373) Pages



**ANT2\_802.11n\_HT20\_UNII 2C**






**ANT2\_802.11n\_HT20\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (45) / (373) Pages



**ANT1\_802.11ac\_VHT20\_UNII 1**






**ANT1\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (46) / (373) Pages



**ANT1\_802.11ac\_VHT20\_UNI1 2C**






**ANT1\_802.11ac\_VHT20\_UNI1 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (47) / (373) Pages



**ANT2\_802.11ac\_VHT20\_UNII 1**






**ANT2\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (48) / (373) Pages



**ANT2\_802.11ac\_VHT20\_UNII 2C**






**ANT2\_802.11ac\_VHT20\_UNII 3**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (49) / (373) Pages



ANT1\_802.11ax\_HE20\_SU\_UNI 1






ANT1\_802.11ax\_HE20\_SU\_UNI 2A






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (50) / (373) Pages



**ANT1\_802.11ax\_HE20\_SU\_UNI 2C**






**ANT1\_802.11ax\_HE20\_SU\_UNI 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (51) / (373) Pages



**ANT2\_802.11ax\_HE20\_SU\_UNI 1**






**ANT2\_802.11ax\_HE20\_SU\_UNI 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (52) / (373) Pages



**ANT2\_802.11ax\_HE20\_SU\_UNI 2C**






**ANT2\_802.11ax\_HE20\_SU\_UNI 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (53) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 1**






**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (54) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 2C**






**ANT1\_802.11ax\_HE20\_26T\_Low\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (55) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 1**






**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (56) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 2C**






**ANT2\_802.11ax\_HE20\_26T\_Low\_UNII 3**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (57) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 1**






**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (58) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 2C**






**ANT1\_802.11ax\_HE20\_26T\_Mid\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (59) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 1**






**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (60) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 2C**






**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (61) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNI 1**



**ANT1\_802.11ax\_HE20\_26T\_High\_UNI 2A**