










**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (38) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNI1 7**






**ANT2\_802.11ax\_HE20\_26T\_Mid\_UNI1 8**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (39) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 5**






**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 6**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (40) / (248) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 7**






**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 8**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (41) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_High\_UNI1 5**






**ANT2\_802.11ax\_HE20\_26T\_High\_UNI1 6**







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (42) / (248) Pages



**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 7**






**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (43) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 5**






**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 6**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (44) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 7**






**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (45) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_Low\_UNI I 5**






**ANT2\_802.11ax\_HE40\_26T\_Low\_UNI I 6**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (46) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 7**






**ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (47) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 5**






**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 6**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (48) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 7**






**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (49) / (248) Pages



ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 5






ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 6






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (50) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 7**






**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (51) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_High\_UNII 5**






**ANT1\_802.11ax\_HE40\_26T\_High\_UNII 6**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (52) / (248) Pages



**ANT1\_802.11ax\_HE40\_26T\_High\_UNII 7**






**ANT1\_802.11ax\_HE40\_26T\_High\_UNII 8**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (53) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_High\_UNI1 5**






**ANT2\_802.11ax\_HE40\_26T\_High\_UNI1 6**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (54) / (248) Pages



**ANT2\_802.11ax\_HE40\_26T\_High\_UNI 7**






**ANT2\_802.11ax\_HE40\_26T\_High\_UNI 8**




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (55) / (248) Pages



**ANT1\_802.11ax\_HE80\_26T\_Low\_UNI I 5**






**ANT1\_802.11ax\_HE80\_26T\_Low\_UNI I 6**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (56) / (248) Pages



ANT1\_802.11ax\_HE80\_26T\_Low\_UNI I 7






ANT1\_802.11ax\_HE80\_26T\_Low\_UNI I 8




**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (57) / (248) Pages



**ANT2\_802.11ax\_HE80\_26T\_Low\_UNI I 5**






**ANT2\_802.11ax\_HE80\_26T\_Low\_UNI I 6**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03423  
 Page (58) / (248) Pages



ANT2\_802.11ax\_HE80\_26T\_Low\_UNI I 7



ANT2\_802.11ax\_HE80\_26T\_Low\_UNI I 8