




ANT1_802.11a_UNII 2C






ANT1_802.11a_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (143) / (373) Pages



ANT2_802.11a_UNII 1






ANT2_802.11a_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03422
 Page (144) / (373) Pages






ANT2_802.11a_UNII 2C






ANT2_802.11a_UNII 3






ANT1_802.11n_HT20_UNII 1



ANT1_802.11n_HT20_UNII 2A



ANT1_802.11n_HT20_UNII 2C






ANT1_802.11n_HT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (147) / (373) Pages



ANT2_802.11n_HT20_UNII 1






ANT2_802.11n_HT20_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (148) / (373) Pages



ANT2_802.11n_HT20_UNII 2C






ANT2_802.11n_HT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (149) / (373) Pages



ANT1_802.11ac_VHT20_UNII 1






ANT1_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (150) / (373) Pages



ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (151) / (373) Pages



ANT2_802.11ac_VHT20_UNII 1






ANT2_802.11ac_VHT20_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (152) / (373) Pages



ANT2_802.11ac_VHT20_UNII 2C






ANT2_802.11ac_VHT20_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (153) / (373) Pages



ANT1_802.11ax_HE20_UNI1 1






ANT1_802.11ax_HE20_UNI1 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03422
 Page (154) / (373) Pages






ANT1_802.11ax_HE20_UNII 2C



ANT1_802.11ax_HE20_UNII 3



ANT2_802.11ax_HE20_UNI 1






ANT2_802.11ax_HE20_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (156) / (373) Pages



ANT2_802.11ax_HE20_UNII 2C




ANT2_802.11ax_HE20_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501





Report No.:
CTK-2021-03422
Page (157) / (373) Pages



ANT1_802.11n_HT40_UNI I 1



ANT1_802.11n_HT40_UNI I 2A





ANT1_802.11n_HT40_UNI I 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (158) / (373) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03422
Page (159) / (373) Pages



ANT2_802.11n_HT40_UNI I 1



ANT2_802.11n_HT40_UNI I 2A





ANT2_802.11n_HT40_UNI I 3C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (160) / (373) Pages




ANT2_802.11n_HT40_UNII 3






CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03422
Page (161) / (373) Pages



ANT1_802.11ac_VHT40_UNI1 1



ANT1_802.11ac_VHT40_UNI1 2A





ANT1_802.11ac_VHT40_UNI1 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (162) / (373) Pages





ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03422
Page (163) / (373) Pages



ANT2_802.11ac_VHT40_UNI1 1



ANT2_802.11ac_VHT40_UNI1 2A





ANT2_802.11ac_VHT40_UNI1 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (164) / (373) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03422
Page (165) / (373) Pages



ANT1_802.11ax_HE40_UNI 1



ANT1_802.11ax_HE40_UNI 2A





ANT1_802.11ax_HE40_UNI 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03422
 Page (166) / (373) Pages





ANT1_802.11ax_HE40_UNI 3




CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03422
Page (167) / (373) Pages



ANT2_802.11ax_HE40_UNI 1



ANT2_802.11ax_HE40_UNI 2A





ANT2_802.11ax_HE40_UNI 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03422
Page (168) / (373) Pages



ANT2_802.11ax_HE40_UNI 3