









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (62) / (373) Pages



**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 2C**






**ANT1\_802.11ax\_HE20\_26T\_High\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (63) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_High\_UNI 1**






**ANT2\_802.11ax\_HE20\_26T\_High\_UNI 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (64) / (373) Pages



**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 2C**





**ANT2\_802.11ax\_HE20\_26T\_High\_UNII 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (65) / (373) Pages



**ANT1\_802.11n\_HT40\_UNI I 1**



**ANT1\_802.11n\_HT40\_UNI I 2A**





**ANT1\_802.11n\_HT40\_UNI I 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (66) / (373) Pages





ANT1\_802.11n\_HT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (67) / (373) Pages



**ANT2\_802.11n\_HT40\_UNI I 1**



**ANT2\_802.11n\_HT40\_UNI I 2A**





**ANT2\_802.11n\_HT40\_UNI I 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (68) / (373) Pages





ANT2\_802.11n\_HT40\_UNI1 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (69) / (373) Pages



**ANT1\_802.11ac\_VHT40\_UNI1**



**ANT1\_802.11ac\_VHT40\_UNI1 2A**





**ANT1\_802.11ac\_VHT40\_UNI1 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (70) / (373) Pages





ANT1\_802.11ac\_VHT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (71) / (373) Pages



**ANT2\_802.11ac\_VHT40\_UNII 1**



**ANT2\_802.11ac\_VHT40\_UNII 2A**





**ANT2\_802.11ac\_VHT40\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (72) / (373) Pages





ANT2\_802.11ac\_VHT40\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2021-03422  
 Page (73) / (373) Pages




ANT1\_802.11ax\_HE40\_SU\_UNI1 1



ANT1\_802.11ax\_HE40\_SU\_UNI1 2A



ANT1\_802.11ax\_HE40\_SU\_UNI1 2C





ANT1\_802.11ax\_HE40\_SU\_UNI1 2C



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (74) / (373) Pages





**ANT1\_802.11ax\_HE40\_SU\_UNI I 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501



Report No.:  
 CTK-2021-03422  
 Page (75) / (373) Pages




**ANT2\_802.11ax\_HE40\_SU\_UNI1 1**



**ANT2\_802.11ax\_HE40\_SU\_UNI1 2A**





**ANT2\_802.11ax\_HE40\_SU\_UNI1 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (76) / (373) Pages





ANT2\_802.11ax\_HE40\_SU\_UNI I 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (77) / (373) Pages



**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 1**



**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 2A**





**ANT1\_802.11ax\_HE40\_26T\_Low\_UNII 2C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (78) / (373) Pages





ANT1\_802.11ax\_HE40\_26T\_Low\_UNI I 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (79) / (373) Pages



**ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 1**



**ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 2A**





**ANT2\_802.11ax\_HE40\_26T\_Low\_UNII 2C**



**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03422  
Page (80) / (373) Pages





ANT2\_802.11ax\_HE40\_26T\_Low\_UNI I 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (81) / (373) Pages



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 1**



**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 2A**





**ANT1\_802.11ax\_HE40\_26T\_Mid\_UNII 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (82) / (373) Pages





ANT1\_802.11ax\_HE40\_26T\_Mid\_UNI1 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (83) / (373) Pages



**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 1**



**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 2A**





**ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 2C**



**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03422  
Page (84) / (373) Pages





ANT2\_802.11ax\_HE40\_26T\_Mid\_UNII 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (85) / (373) Pages



**ANT1\_802.11ax\_HE40\_26T\_High\_UNI 1**



**ANT1\_802.11ax\_HE40\_26T\_High\_UNI 1A**





**ANT1\_802.11ax\_HE40\_26T\_High\_UNI 1C**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-03422  
 Page (86) / (373) Pages





ANT1\_802.11ax\_HE40\_26T\_High\_UNI 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-03422  
 Page (87) / (373) Pages



**ANT2\_802.11ax\_HE40\_26T\_High\_UNI 1**



**ANT2\_802.11ax\_HE40\_26T\_High\_UNI 1A**





**ANT2\_802.11ax\_HE40\_26T\_High\_UNI 1C**



**CTK Co., Ltd.**  
(Ho-dong), 113, Yejik-ro, Cheoin-gu,  
Yongin-si, Gyeonggi-do, Korea  
Tel: +82-31-339-9970  
Fax: +82-31-624-9501

Report No.:  
CTK-2021-03422  
Page (88) / (373) Pages



ANT2\_802.11ax\_HE40\_26T\_High\_UNI I 3