









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (210) / (376) Pages



ANT1_802.11ax_HE20_26T_Low_UNII 2C






ANT1_802.11ax_HE20_26T_Low_UNII 3





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501




Report No.:
CTK-2021-03418
Page (211) / (376) Pages






ANT2_802.11ax_HE20_26T_Low_UNII 1






ANT2_802.11ax_HE20_26T_Low_UNII 2A





ANT2_802.11ax_HE20_26T_Low_UNII 2C



ANT2_802.11ax_HE20_26T_Low_UNII 3



ANT1_802.11ax_HE20_26T_Mid_UNI1 1






ANT1_802.11ax_HE20_26T_Mid_UNI1 2A




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (214) / (376) Pages



ANT1_802.11ax_HE20_26T_Mid_UNI1 2C






ANT1_802.11ax_HE20_26T_Mid_UNI1 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (215) / (376) Pages



ANT2_802.11ax_HE20_26T_Mid_UNII 1






ANT2_802.11ax_HE20_26T_Mid_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (216) / (376) Pages



ANT2_802.11ax_HE20_26T_Mid_UNII 2C






ANT2_802.11ax_HE20_26T_Mid_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (217) / (376) Pages



ANT1_802.11ax_HE20_26T_High_UNI 1






ANT1_802.11ax_HE20_26T_High_UNI 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (218) / (376) Pages






ANT1_802.11ax_HE20_26T_High_UNII 2C



ANT1_802.11ax_HE20_26T_High_UNII 3



ANT2_802.11ax_HE20_26T_High_UNI1 1






ANT2_802.11ax_HE20_26T_High_UNI1 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (220) / (376) Pages





ANT2_802.11ax_HE20_26T_High_UNII 2C






ANT2_802.11ax_HE20_26T_High_UNII 3



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (222) / (376) Pages





ANT1_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (223) / (376) Pages



ANT2_802.11n_HT40_UNII 1



ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C



CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (224) / (376) Pages





ANT2_802.11n_HT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (225) / (376) Pages



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (226) / (376) Pages





ANT1_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (227) / (376) Pages




ANT2_802.11ac_VHT40_UNII 1



ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
(Ho-dong), 113, Yejik-ro, Cheoin-gu,
Yongin-si, Gyeonggi-do, Korea
Tel: +82-31-339-9970
Fax: +82-31-624-9501

Report No.:
CTK-2021-03418
Page (228) / (376) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (229) / (376) Pages



ANT1_802.11ax_HE40_SU_UNI1 1



ANT1_802.11ax_HE40_SU_UNI1 2A





ANT1_802.11ax_HE40_SU_UNI1 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2021-03418
 Page (230) / (376) Pages





ANT1_802.11ax_HE40_SU_UNI I 3




ANT2_802.11ax_HE40_SU_UNI1 1



ANT2_802.11ax_HE40_SU_UNI1 2A





ANT2_802.11ax_HE40_SU_UNI1 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2021-03418
 Page (232) / (376) Pages





ANT2_802.11ax_HE40_SU_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2021-03418
 Page (233) / (376) Pages



ANT1_802.11ax_HE40_26T_Low_UNII 1



ANT1_802.11ax_HE40_26T_Low_UNII 2A



ANT1_802.11ax_HE40_26T_Low_UNII 2C