






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (357) / (659) Pages




ANT1_802.11ax_HE40_52T_Mid_UNII 1





ANT1_802.11ax_HE40_52T_Mid_UNII 2A




ANT1_802.11ax_HE40_52T_Mid_UNII 2C



ANT1_802.11ax_HE40_52T_Mid_UNI I 3



ANT1_802.11ax_HE40_52T_Mid_UNI I 4



ANTO_802.11ax_HE40_52T_High_UNI 1



ANTO_802.11ax_HE40_52T_High_UNI 2A





ANTO_802.11ax_HE40_52T_High_UNI 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (360) / (659) Pages




ANTO_802.11ax_HE40_52T_High_UNI 3





ANTO_802.11ax_HE40_52T_High_UNI 4



ANT1_802.11ax_HE40_52T_High_UNI 1



ANT1_802.11ax_HE40_52T_High_UNI 1A





ANT1_802.11ax_HE40_52T_High_UNI 1C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (362) / (659) Pages



ANT1_802.11ax_HE40_52T_High_UNI 3





ANT1_802.11ax_HE40_52T_High_UNI 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (363) / (659) Pages





ANTO_802.11ax_HE40_106T_Low_UNII 1




ANTO_802.11ax_HE40_106T_Low_UNII 2A



ANTO_802.11ax_HE40_106T_Low_UNII 2C



ANTO_802.11ax_HE40_106T_Low_UNI I 3





ANTO_802.11ax_HE40_106T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (365) / (659) Pages



ANT1_802.11ax_HE40_106T_Low_UNII 1



ANT1_802.11ax_HE40_106T_Low_UNII 2A





ANT1_802.11ax_HE40_106T_Low_UNII 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (366) / (659) Pages





ANT1_802.11ax_HE40_106T_Low_UNI1 3






ANT1_802.11ax_HE40_106T_Low_UNI1 4





ANTO_802.11ax_HE40_106T_Mid_UNI I 1




ANTO_802.11ax_HE40_106T_Mid_UNI I 2A



ANTO_802.11ax_HE40_106T_Mid_UNI I 2C



ANTO_802.11ax_HE40_106T_Mid_UNI I 3





ANTO_802.11ax_HE40_106T_Mid_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (369) / (659) Pages



ANT1_802.11ax_HE40_106T_Mid_UNI 1



ANT1_802.11ax_HE40_106T_Mid_UNI 2A




ANT1_802.11ax_HE40_106T_Mid_UNI 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (370) / (659) Pages



ANT1_802.11ax_HE40_106T_Mid_UNI I 3




ANT1_802.11ax_HE40_106T_Mid_UNI I 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (371) / (659) Pages



ANTO_802.11ax_HE40_106T_High_UNI I 1



ANTO_802.11ax_HE40_106T_High_UNI I 2A




ANTO_802.11ax_HE40_106T_High_UNI I 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (372) / (659) Pages





ANTO_802.11ax_HE40_106T_High_UNI I 3




ANTO_802.11ax_HE40_106T_High_UNI I 4



ANT1_802.11ax_HE40_106T_High_UNI I 1



ANT1_802.11ax_HE40_106T_High_UNI I 2A





ANT1_802.11ax_HE40_106T_High_UNI I 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (374) / (659) Pages



ANTI_802.11ax_HE40_106T_High_UNI I 3





ANTI_802.11ax_HE40_106T_High_UNI I 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (375) / (659) Pages



ANTO_802.11ax_HE40_242T_Low_UNII 1



ANTO_802.11ax_HE40_242T_Low_UNII 2A





ANTO_802.11ax_HE40_242T_Low_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (376) / (659) Pages



ANTO_802.11ax_HE40_242T_Low_UNI I 3





ANTO_802.11ax_HE40_242T_Low_UNI I 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (377) / (659) Pages



ANT1_802.11ax_HE40_242T_Low_UNII 1



ANT1_802.11ax_HE40_242T_Low_UNII 2A





ANT1_802.11ax_HE40_242T_Low_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (378) / (659) Pages






ANT1_802.11ax_HE40_242T_Low_UNI I 3







ANT1_802.11ax_HE40_242T_Low_UNI I 4





ANTO_802.11ax_HE40_242T_High_UNI I 1





ANTO_802.11ax_HE40_242T_High_UNI I 2A




ANTO_802.11ax_HE40_242T_High_UNI I 2C






ANTO_802.11ax_HE40_242T_High_UNI I 3







ANTO_802.11ax_HE40_242T_High_UNI I 4





ANT1_802.11ax_HE40_242T_High_UNI I 1





ANT1_802.11ax_HE40_242T_High_UNI I 2A





ANT1_802.11ax_HE40_242T_High_UNI I 2C





ANT1_802.11ax_HE40_242T_High_UNI I 3







ANT1_802.11ax_HE40_242T_High_UNI I 4



ANTO_802.11ax_HE40_484T_UNI 1



ANTO_802.11ax_HE40_484T_UNI 2A





ANTO_802.11ax_HE40_484T_UNI 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (384) / (659) Pages



ANTO_802.11ax_HE40_484T_UNI 3





ANTO_802.11ax_HE40_484T_UNI 4





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2023-00951
 Page (385) / (659) Pages





ANT1_802.11ax_HE40_484T_UNI I





ANT1_802.11ax_HE40_484T_UNI I 2A




ANT1_802.11ax_HE40_484T_UNI I 2C




ANT1_802.11ax_HE40_484T_UNI 3






ANT1_802.11ax_HE40_484T_UNI 4




ANTO_802.11ac_VHT80_UNII 1




ANTO_802.11ac_VHT80_UNII 2A



ANTO_802.11ac_VHT80_UNII 2C



ANTO_802.11ac_VHT80_UNII 3




ANTO_802.11ac_VHT80_UNII 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (388) / (659) Pages




ANT1_802.11ac_VHT80_UNII 1




ANT1_802.11ac_VHT80_UNII 2A




ANT1_802.11ac_VHT80_UNII 2C




ANT1_802.11ac_VHT80_UNII 3





ANT1_802.11ac_VHT80_UNII 4




ANTO_802.11ax_HE80_26T_Low_UNI I 1




ANTO_802.11ax_HE80_26T_Low_UNI I 2A



ANTO_802.11ax_HE80_26T_Low_UNI I 2C



ANTO_802.11ax_HE80_26T_Low_UNI I 3




ANTO_802.11ax_HE80_26T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (390) / (659) Pages



ANTI_802.11ax_HE80_26T_Low_UNI I 1




ANTI_802.11ax_HE80_26T_Low_UNI I 2A



ANTI_802.11ax_HE80_26T_Low_UNI I 2C



ANTI_802.11ax_HE80_26T_Low_UNI I 3




ANTI_802.11ax_HE80_26T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (391) / (659) Pages



ANTO_802.11ax_HE80_26T_Mid_UNI I 1




ANTO_802.11ax_HE80_26T_Mid_UNI I 2A



ANTO_802.11ax_HE80_26T_Mid_UNI I 2C



ANTO_802.11ax_HE80_26T_Mid_UNI I 3




ANTO_802.11ax_HE80_26T_Mid_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (392) / (659) Pages




ANT1_802.11ax_HE80_26T_Mid_UNI I 1




ANT1_802.11ax_HE80_26T_Mid_UNI I 2A



ANT1_802.11ax_HE80_26T_Mid_UNI I 2C



ANT1_802.11ax_HE80_26T_Mid_UNI I 3



ANT1_802.11ax_HE80_26T_Mid_UNI I 4



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (393) / (659) Pages



ANTO_802.11ax_HE80_26T_High_UNI I 1



ANTO_802.11ax_HE80_26T_High_UNI I 2A



ANTO_802.11ax_HE80_26T_High_UNI I 2C



ANTO_802.11ax_HE80_26T_High_UNI I 3




ANTO_802.11ax_HE80_26T_High_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (394) / (659) Pages



ANTI_802.11ax_HE80_26T_High_UNI I 1




ANTI_802.11ax_HE80_26T_High_UNI I 2A



ANTI_802.11ax_HE80_26T_High_UNI I 2C



ANTI_802.11ax_HE80_26T_High_UNI I 3



ANTI_802.11ax_HE80_26T_High_UNI I 4