




ANT1_802.11ac_VHT20_UNII 1







ANT1_802.11ac_VHT20_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (275) / (659) Pages



ANT1_802.11ac_VHT20_UNII 2C






ANT1_802.11ac_VHT20_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (276) / (659) Pages




ANT1_802.11ac_VHT20_UNII 4



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (277) / (659) Pages



ANTO_802.11ax_HE20_26T_Low_UNII 1



ANTO_802.11ax_HE20_26T_Low_UNII 2A



ANTO_802.11ax_HE20_26T_Low_UNII 2C




ANTO_802.11ax_HE20_26T_Low_UNII 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (279) / (659) Pages




ANTO_802.11ax_HE20_26T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (280) / (659) Pages



ANT1_802.11ax_HE20_26T_Low_UNII 1






ANT1_802.11ax_HE20_26T_Low_UNII 2A




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (281) / (659) Pages



ANT1_802.11ax_HE20_26T_Low_UNII 2C



ANT1_802.11ax_HE20_26T_Low_UNII 3



ANT1_802.11ax_HE20_26T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (283) / (659) Pages




ANTO_802.11ax_HE20_26T_Mid_UNII 1





ANTO_802.11ax_HE20_26T_Mid_UNII 2A






ANTO_802.11ax_HE20_26T_Mid_UNII 2C




ANTO_802.11ax_HE20_26T_Mid_UNII 3






ANTO_802.11ax_HE20_26T_Mid_UNI I 4




ANT1_802.11ax_HE20_26T_Mid_UNII 1



ANT1_802.11ax_HE20_26T_Mid_UNII 2A



ANT1_802.11ax_HE20_26T_Mid_UNI I 2C





ANT1_802.11ax_HE20_26T_Mid_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (288) / (659) Pages





ANT1_802.11ax_HE20_26T_Mid_UNI I 4





ANTO_802.11ax_HE20_26T_High_UNI I 1



ANTO_802.11ax_HE20_26T_High_UNI I 2A



ANTO_802.11ax_HE20_26T_High_UNII 2C




ANTO_802.11ax_HE20_26T_High_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (291) / (659) Pages



ANTO_802.11ax_HE20_26T_High_UNI I 4



ANT1_802.11ax_HE20_26T_High_UNII 1





ANT1_802.11ax_HE20_26T_High_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (293) / (659) Pages



ANT1_802.11ax_HE20_26T_High_UNII 2C



ANT1_802.11ax_HE20_26T_High_UNII 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (294) / (659) Pages




ANT1_802.11ax_HE20_26T_High_UNI I 4



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2023-00951
 Page (295) / (659) Pages



ANTO_802.11ax_HE20_52T_Low_UNII 1



ANTO_802.11ax_HE20_52T_Low_UNII 2A



ANTO_802.11ax_HE20_52T_Low_UNII 2C




ANTO_802.11ax_HE20_52T_Low_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (297) / (659) Pages





ANTO_802.11ax_HE20_52T_Low_UNI I 4



ANT1_802.11ax_HE20_52T_Low_UNI 1



ANT1_802.11ax_HE20_52T_Low_UNI 2A



ANT1_802.11ax_HE20_52T_Low_UNII 2C




ANT1_802.11ax_HE20_52T_Low_UNII 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (300) / (659) Pages





ANT1_802.11ax_HE20_52T_Low_UNI I 4




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00951
 Page (301) / (659) Pages




ANTO_802.11ax_HE20_52T_Mid_UNII 1



ANTO_802.11ax_HE20_52T_Mid_UNII 2A



ANTO_802.11ax_HE20_52T_Mid_UNI I 2C




ANTO_802.11ax_HE20_52T_Mid_UNI I 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (303) / (659) Pages



ANTO_802.11ax_HE20_52T_Mid_UNI I 4



ANT1_802.11ax_HE20_52T_Mid_UNI1 1





ANT1_802.11ax_HE20_52T_Mid_UNI1 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (305) / (659) Pages



ANT1_802.11ax_HE20_52T_Mid_UNI I 2C






ANT1_802.11ax_HE20_52T_Mid_UNI I 3



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (306) / (659) Pages





ANT1_802.11ax_HE20_52T_Mid_UNI I 4



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (307) / (659) Pages



ANTO_802.11ax_HE20_52T_High_UNI 1





ANTO_802.11ax_HE20_52T_High_UNI 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2023-00951
 Page (308) / (659) Pages






ANTO_802.11ax_HE20_52T_High_UNI I 2C




ANTO_802.11ax_HE20_52T_High_UNI I 3




ANTO_802.11ax_HE20_52T_High_UNI I 4




ANT1_802.11ax_HE20_52T_High_UNII 1



ANT1_802.11ax_HE20_52T_High_UNII 2A



ANT1_802.11ax_HE20_52T_High_UNI I 2C



ANT1_802.11ax_HE20_52T_High_UNI I 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (312) / (659) Pages



ANT1_802.11ax_HE20_52T_High_UNI I 4



ANTO_802.11ax_HE20_106T_Low_UNII 1





ANTO_802.11ax_HE20_106T_Low_UNII 2A




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00951
 Page (314) / (659) Pages





ANTO_802.11ax_HE20_106T_Low_UNII 2C





ANTO_802.11ax_HE20_106T_Low_UNII 3



ANTO_802.11ax_HE20_106T_Low_UNII 4



ANT1_802.11ax_HE20_106T_Low_UNII 1



ANT1_802.11ax_HE20_106T_Low_UNII 2A