









CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (223) / (427) Pages





ANTO_802.11ax_HE40_26T_Mid_UNII 7






ANTO_802.11ax_HE40_26T_Mid_UNII 8






ANT1_802.11ax_HE40_26T_Mid_UNII 5






ANT1_802.11ax_HE40_26T_Mid_UNII 6





ANT1_802.11ax_HE40_26T_Mid_UNII 7



ANT1_802.11ax_HE40_26T_Mid_UNII 8



ANTO_802.11ax_HE40_26T_High_UNII 5






ANTO_802.11ax_HE40_26T_High_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (227) / (427) Pages





ANT0_802.11ax_HE40_26T_High_UNII 7






ANT0_802.11ax_HE40_26T_High_UNII 8






ANT1_802.11ax_HE40_26T_High_UNII 5






ANT1_802.11ax_HE40_26T_High_UNII 6





ANT1_802.11ax_HE40_26T_High_UNII 7



ANT1_802.11ax_HE40_26T_High_UNII 8



ANT0_802.11ax_HE40_52T_Low_UNII 5






ANT0_802.11ax_HE40_52T_Low_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (231) / (427) Pages





ANT0_802.11ax_HE40_52T_Low_UNII 7



ANT0_802.11ax_HE40_52T_Low_UNII 8



ANT1_802.11ax_HE40_52T_Low_UNII 5






ANT1_802.11ax_HE40_52T_Low_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (233) / (427) Pages



ANT1_802.11ax_HE40_52T_Low_UNII 7






ANT1_802.11ax_HE40_52T_Low_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (234) / (427) Pages



ANTO_802.11ax_HE40_52T_Mid_UNII 5






ANTO_802.11ax_HE40_52T_Mid_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (235) / (427) Pages





ANTO_802.11ax_HE40_52T_Mid_UNII 7






ANTO_802.11ax_HE40_52T_Mid_UNII 8






ANT1_802.11ax_HE40_52T_Mid_UNII 5



ANT1_802.11ax_HE40_52T_Mid_UNII 6



ANT1_802.11ax_HE40_52T_Mid_UNII 7






ANT1_802.11ax_HE40_52T_Mid_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (238) / (427) Pages



ANTO_802.11ax_HE40_52T_High_UNII 5





ANTO_802.11ax_HE40_52T_High_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (239) / (427) Pages





ANT0_802.11ax_HE40_52T_High_UNII 7






ANT0_802.11ax_HE40_52T_High_UNII 8






ANT1_802.11ax_HE40_52T_High_UNII 5






ANT1_802.11ax_HE40_52T_High_UNII 6





ANT1_802.11ax_HE40_52T_High_UNII 7






ANT1_802.11ax_HE40_52T_High_UNII 8






ANTO_802.11ax_HE40_106T_Low_UNII 5






ANTO_802.11ax_HE40_106T_Low_UNII 6





ANT0_802.11ax_HE40_106T_Low_UNII 7



ANT0_802.11ax_HE40_106T_Low_UNII 8



ANT1_802.11ax_HE40_106T_Low_UNII 5






ANT1_802.11ax_HE40_106T_Low_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (245) / (427) Pages



ANTI_802.11ax_HE40_106T_Low_UNII 7






ANTI_802.11ax_HE40_106T_Low_UNII 8





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2023-00952
 Page (246) / (427) Pages



ANT0_802.11ax_HE40_106T_Mid_UNII 5






ANT0_802.11ax_HE40_106T_Mid_UNII 6






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2023-00952
 Page (247) / (427) Pages





ANT0_802.11ax_HE40_106T_Mid_UNII 7






ANT0_802.11ax_HE40_106T_Mid_UNII 8






ANT1_802.11ax_HE40_106T_Mid_UNII 5



ANT1_802.11ax_HE40_106T_Mid_UNII 6



ANT1_802.11ax_HE40_106T_Mid_UNII 7



ANT1_802.11ax_HE40_106T_Mid_UNII 8