

The errors that need changing on the 731 form are:

- The equipment code needs changing from CYY to DSS.
- The transmitter operations frequency reads 3850-5725MHz and the RF 1.0 watt when it should be transmitters operation frequency 5725~5850 MHz with base unit RF output power 0.066 watts and handset unit RF output power 0.00484 watts