

P0940021      Response to RT – 14 July 2009

1. The RF Test report page 14 of 32 top table lists 429.95MHz, but it appears that this was supposed to be listed as 150.05 MHz. Please confirm the frequency of operation and update the application exhibits accordingly.

The frequency error was a typo and the top table on page 14 has been corrected to read 150.05 MHz.