


Prüfbericht - Nr.: 12604515 001
Test Report No.:

Seite 38 von 41
Page 38 of 41

8. Photographs of test setup


Photograph 1: Set-up for Conducted Testing



Prüfbericht - Nr.: 12604515 001
Test Report No.:

Seite 39 von 41
Page 39 of 41

Photograph 2: Set-up for Radiated Emission, EUT Configuration Y-axis



Photograph 3: Set-up for Radiated Emission, EUT Configuration Y-axis

