


Prüfbericht - Nr.: 12604515 002
Test Report No.:

Seite 41 von 47
Page 41 of 47

9. Photographs of test setup


Photograph 1: Set-up for Conducted Testing




Prüfbericht - Nr.: 12604515 002
Test Report No.:

Seite 42 von 47
Page 42 of 47

Photograph 2: Set-up for Radiated Emission, EUT Configuration



Photograph 3: Set-up for Radiated Emission, EUT Configuration




Prüfbericht - Nr.:
Test Report No.:


12604515 002

Seite 43 von 47
Page 43 of 47

Photograph 4: Set-up for Radiated Emission, EUT Configuration, X-axis




Photograph 5: Set-up for Radiated Emission, EUT Configuration, Y-axis



Prüfbericht - Nr.: 12604515 002
Test Report No.:

Seite 44 von 47
Page 44 of 47

Photograph 6: Set-up for Radiated Emission, EUT Configuration, Z-axis



Photograph 7: Set-up for Conducted Emission, EUT Configuration



Prüfbericht - Nr.: 12604515 002
Test Report No.:

Seite 45 von 47
Page 45 of 47

Photograph 8: Set-up for Conducted Emission, EUT Configuration



Photograph 9: Set-up for Conducted Emission, EUT Configuration

