			65 mm	i		
		MODEL	NX60	3	Clarion	
		12V ⊖ GROUND 15A max				
		AM	530-1710kHz	FM 87.9-10	7.9MHz	
	RSS standard (1) this device	d(s).Operation	Part 15 of FCC Rules a is subject to the follow use interference, and (rference that may cau	ving two conditions: 2) this device must a	accept any	
	Le presnt appareil est conforme aux la partie 15 des regles de la FCC et CNR d'industrie Canada applicables aux appareils radio exempts de licence.L'exploitation est autorisee aux deux conditions suivantes: (1) l'appareil ne doit pas produire de brouillage, et (2) l'utilisateur de l'appareil doit accepter tout brouillage radioelectrique subi.mem si le brouillage est susceptible d'en compromettre le fonctionnement					
65 mm	THIS DEVICE COMPLIES WITH DHHS RULES 21 CFR CHAPTER I SUBCHAPTER J APPLICABLE AT DATE OF MANUFACTURE.					
	This product includes technology owned by Microsoft Corporation and cannot be used or distributed without a license from MSLGP.					
	Manufactured under license from Dolby Laboratories. "Dolby" and the double-D symbol are trademarks of Dolby Laboratories.					
	This Class B digital apparatus complies with Canadian ICES-003. Cet appareil numérique de la classe B est conforme à la norme NMB-003 du Canada.					
	CLARION CO.,LTD. 7-2,SHINTOSHIN,CHUO-KU,SAITAMA-SHI,SAITAMA-KEN,JAPAN					
	MANUFACTU IC: 419C-NX SERIAL No.	603	-		D ID No.: B020554 CC ID:AX2NX603	
Ļ	QY-1010U-A]	LF	Clarion Co., Ltd. MADE IN JAPAN 276-1168-00	

PRECAUTIONS

- For your safety, the driver should not watch the DVD video/movie data or operate the controls while driving. Please note that watching and operating the DVD video/movie data while driving are prohibited by law in some countries. Also, while driving, keep the volume to a level at which external sounds can be heard.
- When the inside of the car is very cold and the player is used soon after switching on the heater, moisture may form on the disc (DVD/CD) or the optical parts of the player and proper playback may not be possible. If moisture forms on the disc (DVD/CD), wipe it off with a soft cloth. If moisture forms on the optical parts of the player, do not use the player for about one hour. The condensation will disappear naturally allowing normal operation.
- 2. Driving on extremely bumpy roads which cause severe vibration may cause the sound to skip.
- 3. This unit uses a precision mechanism. Even in the event that trouble arises, never open the case, disassemble the unit, or lubricate the rotating parts.
- 4. This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules.
 These limits are designed to provide reasonable protection against harmful interference in a residential installation.
 This equipment generates, uses, and

can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to consult the dealer or an experienced radio/TV technician for help.

5. Under Industry Canada regulations, this radio transmitter may only operate using an antenna of a type and maximum (or lesser) gain approved for the transmitter by Industry Canada. To reduce potential radio interference to other users, the antenna type and its gain should be so chosen that the equivalent isotropically radiated power (e.i.r.p.) is not more than that necessary for successful communication.

■ INFORMATION FOR USERS:

CHANGES OR MODIFICATIONS TO THIS PRODUCT NOT APPROVED BY THE MANUFACTURER WILL VOID THE WARRANTY AND WILL VIOLATE FCC APPROVAL.

NX603		
WERE .	r	Clarkon
12 12		Date: 164, max
11.040.0940		1.91 04 04 104 104 10
LANGE COMPANY	NUMBER DA	CLASSES AND
11. AND A 12	11112 a	a decision a
AN AMERICAN ST		CONCREMENTED FOR
	Street Aller	Contraction of the second
and and in p	and the second se	Takes for and read
Part at a	and the second	Part of
STREET, DOOR	CONTRACTOR OF DESIGNATION	IL IS MAN
	_	
2.1		Andrea AllElen
MAR No.		(T) second
		19 💳
FX503		
MODEL		clarion
	GROUND	
AM 530-	1710kHz FM	87.9-107.9MHz
THIS DEVICE COMPLIES	WITH PART 15 OF THE	FCC RULES.
(1)THIS DEVICE MAY NO (2)THIS DEVICE MUST A	CAUSE HARMFUL IN	FCC RULES. TWO CONDITIONS: TERFERENCE, AND ENCE RECEIVED. UNDESIRED OPERATION.
NCLUDING INTERFEREI THIS DEVICE COMPLIES	NCE THAT MAY CAUSE WITH DEHS RULES 21	UNDESIRED OPERATION. CFR CHAPTER I SUBCHAPTER J
APPLICABLE AT DATE Of his product indudes tech	F MANUFACTURE	at: Corporation and sannot he used
This Class B dig tal appara	tus complies with Canad	ian ICES-203
Ce: appareil numér cue de	a classe E est conformé	a a norma NMB-303 cu Canada.
CLARION GO., LTD. 7-2, SH NTOSHIN, CHUOH	KU,SATIAMA-SH,SATIA	MA-KHN, APAN
		Bluetocth QD_D_No
SERIAL No.		FGGILLANNANA
·		ſĒ 💳
02.30101.4	-	276-1215-00
	· · · ·	1
	$ \longrightarrow$	L
	$ \longrightarrow $	}

Operation Panel/Generalities

For a longer service life, be sure to read the following cautions.

- Do not allow any liquids on the set from drinks, umbrellas, etc. Doing so may damage the internal circuitry.
- Do not disassemble or modify the set in any way. Doing so may result in damage.Also, subjecting the operation panel to shocks may result in breakage, deformation, or other damage.
- Do not let cigarettes burn the display. Doing so may damage or deform the cabinet.
- If a problem should occur, have the set inspected at your store of purchase.
- The optional remote control unit may not work if the remote control sensor is exposed to direct sunlight.
- In extremely cold weather, the display movement may slow down and the display may darken, but this is not a malfunction. The display will work normally when the temperature increases.
- Small black and shiny spots inside the operation panel are normal for LCD products.
- The touchkeys on the display operate when slightly touched. Do not press the touchkey screen with much force.
- Do not push the case surrounding the touchkey panel with much force. This may cause malfunctioning of the touchkeys.