Interactive Technologies Inc

EXHIBIT A ID Label / Location



S4006

Household Fire and Burglary Warning System Control Unit ISSUE NO: AE6558

GE Interlogix Inc. 2266 North 2nd Street North St. Paul, MN 55109 1-800-777-1415

Transformer: ITI Part#: 22-109

Canada: 22-109-CN

Power Input: 120 VAC, 125 mA Power Output: 9 VAC, 700 mA

Model: 60-875-95R 60-875-00-3-SPN 60-875-01-3-SPN

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code ANSI/NFPA 72-1993 (National Fire Protection Association, Batterymarch Park, Quincy, MA 02669) INTERNAL BATTERY:
6VDC The battery is automatically tested every 4 hours. REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT ONLY: Yuasa Battery America, Part No.NP1.2-6 Lead Acid or Topin Battery Ltd Part No. TP6-1.3

Wiring Diagram: See installation Manual 466-1873. This system is intended to be checked by a qualified technician at least every three years.

Ringer Equivalence 0.1B (AC) Load Number 0.1

This device complies with FCC rules Part 15. Operation is subject to the Complies with Part 68 ACTA Rules

ACTA Reg. No. B4ZUSA-46042-AL-T

This device complies with FCC rules Part 15. Operation is subject to the following two conditions: 1)this device may not cause harmful interference following two conditions: 1)this device may not cause harmful interference that maybe received. and (2) this device must accept any interference that maybe received, including interference that may cause undesired operation.

WARNING:

FCC ID: B4Z-787E-SIMON IC: 867A 787SIMON US Patents 4,855,713, 4,864,636 and others pending

DO NOT CONNECT TO A RECEPTACLE CONTROLLED BY A SWITCH. HIGH VOLTAGE; DISCONNECT TELCO BEFORE SERVICING. CAUTION: IMPROPER CONNECTIONS MAY 422-1932-04 Rev. D RESULT IN DAMAGE TO THE EQUIPMENT.

05/23/02 2:12 PM

FCC ID: B4Z-787E-SIMON

W:\iti2vol2\PRJ\DEG\ACTIVE\60-875-95R Simon 3 Domestic\Approvals-Listings-Technical File\FCC\Part 15 Submittle\peices\id label.DOC