

This device complies with FCC rules Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) This device must accept any interference that may be received including interference that may cause undesired operation.

FCC ID: B4Z-010C-SIMON

GE Security, Inc.
1275 Red Fox RD
Arden Hills MN 55112

Complies with Part 68 ACTA Rules

ACTA Reg. No: US: B4ZAL02B55910

Ringer Equivalence: 0.2B

Canada:

Load Number:

US PATENTS 4865713, 4864636, 5770996, 5736927

422-4146

Simon XT Label Location



WARNING: 422-2258 Rev. A
DO NOT CONNECT TO A RECEPTACLE CONTROLLED BY A SWITCH. HIGH VOLTAGE; DISCONNECT TELCO BEFORE SERVICING.

This device complies with FCC rules Part 15. Operation is subject to the following two conditions: (1) This device may not cause harmful interference and (2) This device must accept any interference that may be received including interference that may cause undesired operation.

FCC ID: B428-SIMON
GE Security, Inc.
1376 Max Fax Rd.
Albany, NY 12212
Complies with Part 68 ACTA Rules
ACTA Reg. No. US: B428-02855910
Ringer Equivalent: 0.28
Cordless: YES
US PATENTS: 4888719, 4884836, 4770880, 4738827

**SECURITY
SIGNALING**



Residential
Fire Alarm and
Security Equipment

3PAW S4006
Also Classified in Accordance
with ANSI/SIA CP-01-2000

422-4253

This Equipment should be installed in accordance with chapter 2 of the National Fire Alarm Code and NFPA 72 (2001) (National Fire Protection Association, Batterymarch Park, Quincy, MA 02269). REPLACE BATTERY EVERY 3-5 YEARS WITH EXACT REPLACEMENT IT O.H.V. OR Security Part No. 42-814 Lead Acid. For UL/ISA Requirements and Wiring Diagram See Installation Manual 400-2285.

Model Number: 600-1054-95R

Power Input: 120 Vac 100 mA Transformer Part: 23-121
Power Output: 5Vdc 3.3A GE Security
1279 Rad Fox Rd, Arden
NC 28404
(800) 777-3524
US Patents 4,851,713 4,804,836 and others pending

444-1729