

HP considered the FCC's request to "Please inform grantee to consider including some folio use instructions in the manual, with respect to improving wireless performance and RF exposure." However, the device is already programmed to display the following warning when the device is used without the folio, or with a folio that does not trigger the sensor (causing the slate to operate at reduced power):

