

September 25, 2009

Nemko Canada Inc
303 River Road
Ottawa, Ontario, Canada
K1V 1H2

Attn: Director of Certification
Ref: FCC ID BYMCOM400

The COM400 does not have an output power tune up procedure per Sec. 2.1046B of FCC Title 47.

Sincerely,



Karl Knoblock
Electrical Engineering Manager