

Internal PIFA PCB antenna. Disabled by Firmware at factory



17-000793_B



88V8388-BDK1


88V8388-BDK1
AGSHP 2
0525 A2P ES
TV

25P40VP
17 24508

GB5
18

Flexible Stainless Steel

3 4 5 6 7 8 9



Omni EV5C Hardware (not for sale)
SN. OMEV5C-0059 FW Ver. 4.3.9.P1.29.P0
Lead - Free Yes
Marvell Silicon 8388 A2 / 8030 B1B
MAC address 00-0D-3A-7A-DE-5D



MLU4020-D68 (LF)
1156H000079
F08

OK
MADE IN
TAIWAN
12

Microsoft



