



DUT with Harness and Serial Interface



56043255XX



DAIMLERCHRYSLER PCL: TBD
PROD. DATE/SHIFT: 3423/1
MAIN S/W REV: 4.8.0 H/W REV: 000A 75813
FCC ID: TBD
IC: TBD



VS9632C000YA

JOHNSON CONTROLS INTERIORS

DR6

DUT (J1850 Diff) top

JOHNSON
CONTROLS

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:

k:\PLUS\11830-05PA\electronics\engineering\parts record.xls

Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

DUT (J1850 Diff) bottom

OSPA

4.8.0~~9~~

J1850
Plain



05091004XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3423/1

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

FCC ID: TBD

IC: TBD



VS9630C003ZA

JOHNSON CONTROLS INTERIORS

DUT (J1850 Gen) top

Any modifications/analysis done to this part **MUST** be recorded in:
K:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

!!! WARNING !!!

JOHNSON
CONTROLS

DUT (J1850 Gen) bottom



05064013XX



DAIMLERCHRYSLER PCL: TBD

PROD. DATE/SHIFT: 3283/2

MAIN S/W REV: 4.8.0 H/W REV: 000A 75813

BUS S/W REV: 1.0

FCC ID: TBD

IC: TBD



VS8734C0014A

JOHNSON CONTROLS INTERIORS

CAN

DUT (CAN) top

JOHNSON
CONTROLS

!!! WARNING !!!

Any modifications/analysis done to this part **MUST** be recorded in:
K:\PLUS\1830-05PA\electronics\engineering\parts record.xls
Failure to comply compromises the ability to root cause issues,
leading to significant project delays and wasted time.

DUT (CAN) bottom