

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE

External Photographs



Figure 1. EUT, Front

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 2. EUT, Back

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE




Figure 3. EUT, Top

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE




Figure 4. EUT, Bottom

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 5. EUT, Right Side

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 6. EUT, Left Side

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 7. HMI Panel Removed – Front

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 8. HMI Panel Removed – Back

US Tech Test Report
FCC ID:
IC:
Test Report Number:
Issue date:
Model:

FCC Part 15.209/249
CN2-CP1000BLE
1007A-CP1000BLE
20-0304
November 30, 2020
CP1000BLE



Figure 9. HMI Panel Gasket