

Annex A: Photographs of the Test Set-up

Photo 1: Power Line Conducted Emission Test




Photo 2: Power Line Conducted Emission Test



Test report no.: 1-5753/12-02-15



Photo 3: Radiated Emission



Photo 4: Radiated Emission

