
SD9 PCB Updates and comments

D.M. 8/10/2019

Moved power supply away from RF section

Memory/flash moved to right

When power supply moved to left, moved SAW filter closer to upconverter. Now under a shield



Same Ethernet drivers

Added DC/ESD input surge protection

CODEC moved slightly for production ease

No changes in the TRANSMIT section or TX parts changed.



