

Response to E05-000026-1

1. The user's manual is complete. The module is very simple and the manual does not contain a lot of information.
2. An additional internal photo has been uploaded. Also, the component that looks like it is attached to the board with 6 Allen screws is attached directly to the ground plane. It is not attached to the board. There is a cutout in the board for it.
3. The correct emissions designators should be GXW and G7W. Please revise the 731 form. The test report has been revised and uploaded.
4. The factory tune-up procedure is in the folder Parts List/Tune Up Info on the TCB drive.
5. This device has no antenna and the customer has no say in how the antenna is installed.
6. The DC voltages information is in the Test Report folder on the TCB drive.
7. Item 7 This is not a change from the norm. The final unit has tape shielding on all open holes and ports. It looks prettier than the copper but all are covered.
8. The test report has been revised to correct this typo.