

From: Greg Butler [gbutler@pwav.com]
Sent: Wednesday, October 05, 2005 9:56 AM
To: Kendall, Chuck
Subject: RE: Missing tune up procedure

From: Greg Butler [mailto:gbutler@pwav.com]
Sent: Wednesday, October 05, 2005 9:23 AM
To: Kendall, Chuck
Subject: RE: Missing tune up procedure

This amplifier requires no tune up.

-----Original Message-----

From: Kendall, Chuck [mailto:chuck.kendall@ckc.com]
Sent: Wednesday, October 05, 2005 9:13 AM
To: Greg Butler
Cc: info@ckccertification.com
Subject: Missing tune up procedure

Hi Greg,

The FCC is requesting a tune up procedure or a statement that there is none for your model EHP19, Integrated Power Transceiver (IPT), This is FCC ID: E675JS0077.

Please send us either item but as soon as possible.

Thank you,

Chuck Kendall

Senior EMC Consultant

CKC Certification Services

Tel: (209) 966-5240

Email: chuckk@ckc.com