



+1.714.466.1000 fax. +1.714.466.5800

23 June 2009

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Re: Tune-up Procedure

To Whom It May Concern:

In reference to the application under FCC ID: E675JS0110 as required by rule part 2.1033(c)(9) please be advised that there is no tune-up procedure for this product. All tuning is performed in the factory prior to shipment and there are no operator adjustable controls.

Sincerely,

Jeffrey A. Dale

Reliability / Regulatory Engineering

get a. Ene

(714) 466-1476

(714) 466-5807 FAX

jdale@pwav.com