

Revised Tune-Up Procedure – 81863

No tune-up procedures are required because the SL40 VHF Com can only be serviced and tuned at the GARMIN AT service facility in Salem, Oregon.