

Appendix L: Internal Photographs



Photograph 10: Front



Photograph 11: Back

Note - There are no components under the battery. The TX is at the top of the PCB, above the horizontal break in the ground plane (about the top 20% of the PCB).

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: Fleetwood Group, Inc.
Model: WRS8200
Standards: FCC 15.247/IC RSS-210
FCC/IC ID: FBRWRS8200/1859A-WRS8200
Report #: 2009237



Photograph 12: Side

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>


Client: Fleetwood Group, Inc.
Model: WRS8200
Standards: FCC 15.247/IC RSS-210
FCC/IC ID: FBRWRS8200/1859A-WRS8200
Report #: 2009237




Photograph 13: Side

Rhein Tech Laboratories, Inc.
360 Herndon Parkway
Suite 1400
Herndon, VA 20170
<http://www.rheintech.com>

Client: Fleetwood Group, Inc.
Model: WRS8200
Standards: FCC 15.247/IC RSS-210
FCC/IC ID: FBRWRS8200/1859A-WRS8200
Report #: 2009237



Photograph 14: End



Photograph 15: End