

REV	DATE	ORIG	DESCRIPTION	ER#
A	9/3/03	MJC	3.3V reg package change	

D

D

C


C

B

B

A

A



Must use 0.63" fiberglass due to Digi-Connect pins

Lassen SK-II

Void power planes under ethernet signals