Helen Zhao

Subject: FW: Broadxent Pte Ltd, FCC ID: GX5-CB2431, Assessment NO.: AN05T4522, Notice#1 Exhibit-C-Test_Rep Exhibit-K-O_D_revis ort_revised.... ed.pdf ----Original Message-----From: SS Sent: Thursday, February 03, 2005 12:39 AM To: Helen Zhao Cc: R00/??? Subject: Re: Broadxent Pte Ltd, FCC ID: GX5-CB2431, Assessment NO.: AN05T4522, Notice#1 Dear Helen, Replying your questions. #1 The setting is corrected. Please refer to the revised test report. #2 The setting is corrected. Please refer to the revised test report. #3 Please refer to the revised operation description file. Best regards, S. S. Liou ----Original Message-----From: Compliance Certification Services [mailto:hzhao@ccsemc.com] Sent: Monday, January 31, 2005 4:11 PM Subject: Broadxent Pte Ltd, FCC ID: GX5-CB2431, Assessment NO.: AN05T4522, Notice#1 Question #1: The plots of "NUMBER OF HOPPING FREQUENCY USED" shows an incorrect setting was used: RBW=100KHz, while the span was 83.500MHz. The correct setting should be: RBW>=1% of the span. Please re-submit the plots with correct setting. Question #2: The plots of "100 kHz BANDWIDTH OF BAND EDGES MEASUREMENT" shows an incorrect setting was used: RBW=100KHz, while the span was 50MHz. The correct setting should be: RBW>=1% of the span. Please re-submit the plots with correct setting. Question #3: Please resubmit Operation Description. The file named "O-D" in the filing is actually an antenna specification only.

Best Regards, Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.